

Chapter 10: Phase Transformations

ISSUES TO ADDRESS...

- _____ one phase into another takes time.

- How does the rate of _____ depend on time and temperature?
- Is it possible to slow down transformations so that non-equilibrium _____ are formed?
- Are the mechanical properties of non-equilibrium structures more desirable than _____ ones?

Chapter 10 - 1

Phase Transformations

Nucleation

- nuclei (seeds) act as templates on which crystals grow
- for nucleus to form rate of addition of atoms to nucleus must be faster than rate of loss
- once nucleated, growth proceeds until equilibrium is attained

Driving force to nucleate increases as we increase ΔT

- _____ (eutectic, eutectoid)
- _____ (peritectic)

Small supercooling \rightarrow _____ - few nuclei - _____ crystals


Large supercooling \rightarrow _____ - many nuclei - _____ crystals

Chapter 10 - 2

Solidification: Nucleation Types

- **Homogeneous nucleation**
 - nuclei form in the bulk of liquid _____
 - requires considerable _____ (typically 80-300°C)
- _____ nucleation
 - much easier since _____ "nucleating surface" is already present—e.g., mold wall, impurities in liquid phase
 - only very slight _____ (0.1-10°C)

Chapter 10 - 3



Solidification

$$r^* = \frac{-2\gamma T_m}{\Delta H_f \Delta T}$$

$r^* =$ critical radius

$\gamma =$ surface free energy

$T_m =$ melting temperature

$\Delta H_f =$ latent heat of ...

$\Delta T = T_m - T =$ supercooling

Note: ΔH_f and γ are _____ dependent on ΔT

$\therefore r^*$ _____ as ΔT increases

For typical ΔT $r^* \sim 10$ nm


Chapter 10 - 5


Rate of Phase Transformations


Kinetics - study of reaction rates of phase transformations


- To determine reaction rate – measure degree of _____ as function of time (while holding temp constant)
 - How is degree of _____ measured?
 - _____ – many specimens required
 - electrical conductivity measurements – on _____ specimen
 - measure _____ of sound waves – on single specimen

Chapter 10 - 6









Isothermal Heat Treatment Example Problems

On the isothermal transformation diagram for a 0.45 wt% C, Fe-C alloy, sketch and label the time-temperature paths to produce the following microstructures:

- 42% proeutectoid ferrite and 58% coarse pearlite
- 50% fine pearlite and 50% bainite
- 100% martensite
- 50% martensite and 50% austenite

Chapter 10 - 20

